




## Quick Tech TIPS on aligning the Active Autowerke GEN 3 rear exhaust



Adjustment of the exhaust can be changed by allowing sealing gasket ring "D" to move forward or backwards before tightening the flanges "A" to "A1" and "B" to "B1". This adjustment will allow for movement left to right and right to left for proper clearance at cross-member and trunk spare wheel well.

Sealing gasket "D" should be a new one, and allowed to move along the passenger side pipe behind the catalyst, do not use the original location of sealing gasket "D" from the original exhaust. **The gen 3 exhaust may require a new location for proper fitment.**

Sealing gasket "C" will seal the exhaust gases even if the driver's side pipe is not 100% straight.

Hint: Sometimes the catalyst pipes are not straight inside the tunnel, this can be checked very easily by looking at the rubber hangers, they should be hanging in a vertical position, if the catalyst is crooked, the Gen 3 exhaust will not fit properly